ASSEMBLY OF APRON TABLE



TOOLS REQUIRED:

NONE

a) MATCHING LEG 1 TO CORNER 1 PLACE BOLTS THROUGH CORNER BRACKET

(all four legs & corners are numbered)





b) USING HARDWARE PROVIED (Qty 8: 5/16 Lock Washers & Qty 8: 5/16 - 18 Wing Nuts)...



c) ...ATTACH LEGS TO CORNER BRACKETS

